

NP3TT-1

0.173" (4.4 mm) BANTAM-TYPE MINIATURE PLUGS



2. Cable preparation



3. Insert the prepared cable into the connector




4.) Soldering

Solder the inner leads to the solder cups. Make sure that the central cup is properly covered with solder thus securing the threaded joint between tip and cup.



5. Hex-Crimping


To connect the ground and for proper cable retention: crimp the rear part of the connector with the NEUTRIK Crimp tool.




(6.) Move forward bushing and cover as far as easily possible.



Recommendation: Check electrical connection before final assembly.



Insert into the tool - press together.





NEUTRIK AG NEUTRIK Zürich AG NEUTRIK USA Inc. NEUTRIK (UK) Ltd. T: +423/2372424 F: +423/2325393
T: +41 44/7365010 F: +41 44/7365011
T: +1732/9019488 F: +1732/9019608
T: +44 1983/811441 F: +44 1983/811439

Update: 08.08.2007

NEUTRIK Vertriebs GmbH
NEUTRIK France
NEUTRIK Tokyo Ltd.
NEUTRIK Hong Kong Ltd.

DE/NL/AT T FR T JP T

/AT T: +49 8131/280 890 F: +49 8131/280 830 T: +33 1/4131 6750 F: +33 1/4131 0511 T: +81 3/3663 4733 F: +81 3/3663 4796 T: +852/2687 6055 F: +852/2687 6052

www.neutrik.com

Draft. Nr.: BDA 030 / 3102M1341

СН

USA



